

Patina Railyard Oak Batch #127201



Pioneer millworks
RECLAIMED & SUSTAINABLE WOOD PRODUCTS

Our Railyard Oak has a distinct look with rugged texture, a rich range of grey, taupe, and tan color tones, and occasional rusty stains and strap marks. Primarily Oak, a small percentage of other hardwoods may be included in the mix.

Source Location: Alabama

This batch of material was sourced from shipping yards in Alabama where a mix of 2 x 6" and 4 x 4" boards were used as dunnage to stack and store metal piping. Ferrous staining from where the metal was in contact with the wood, and nail holes where triangular blocks were once attached to prevent pipes from rolling off, are testament to this material's past life.



Pioneer Millworks Patina—Railyard Oak

1/2020

CUT AND PASTE SPECIFICATION INTO APPROPRIATE CSI DIVISION

06 42 00—Wood Paneling

MANUFACTURER

Pioneer Millworks
1180 Commercial Drive
Farmington, NY 14425
Phone: 800-951-9663

Pioneer Millworks
2609 SE 6th Avenue
Portland, OR 97202
Phone: 503-719-4800

MATERIALS

1. **Product Name:** Patina Railyard Oak
2. **Species/Description:** Domestic Red and White Oak with original patina; up to 40% may be a mix of other Domestic Hardwood species.
3. **Source:** Reclaimed shipping dunnage
4. **Color:** Tones may range from brown to grey with darker perpendicular striping. Unlimited color variation is inherent to the product
5. **Grade:** Railyard Patina
6. **Dimensions:**
 - Solid**
TH—1/2"
WD—3" to 5" as specified
LG—18" to 108" random
 - Engineered**
TH—N.A.
WD—N.A.
LG—N.A.
7. **Milling:** Surfaced on three faces (S3S)
8. **Finish:** Unfinished unless specified otherwise
9. **Hardness:** 1060-1360
(Janka Ball Test ASTM D1037-96A, Natural wood products have no minimum hardness since hardness is a characteristic of species and cannot be controlled)
10. **FSC Claim:** (SCS-COC-003998)
 - Solid:** FSC Recycled 100%
 - Engineered:** N.A.

ADDITIONAL INFORMATION

Heartwood: No restriction

Grain: No restriction

Knots: No limitations on sound knots, surface defects from chipped or open knots may be present.

Texture: This mixture shows a varied pattern of saw marks, wear patterns, colors and textures. Overwood of up to 1/8" can be expected.

Voids: Fastener holes and open knots can be present and occasionally reach 1/2" in diameter. Surface defects from insect marks, including pin holes may be present. Larger voids are occasionally included to preserve long lengths.

Discoloration: Ferrous staining from previous fasteners may be present.

Checks: Structural checks not affecting the integrity of the plank, once installed, are allowed.

Moisture Content: Kiln dried 6–9% prior to milling.

LEED INFORMATION

MRC3: Materials Reuse

(materials used for this credit cannot be applied to MRC4 or MRC5)

MRC4: Recycled Content, 100% Post-Consumer Recycled Content

(materials used for this credit cannot be applied to MRC3 or MRC7)

MRC5: Regional Materials (call for details)

MRC7: Solid Materials are FSC Recycled 100%

RECOMMENDED OVERAGE

Recommend 7–12% additional material for on-site grading, trimming and installation factors



The mark of responsible forestry



Information is deemed reliable but subject to change. All photos for representation only. Additional information available at our website or call our wood design experts.