Mixed Hardwoods—Settlers' Plank



A mosaic of hardwood species native to the Northeastern US, you'll find things like Ash, Elm, Hickory, Beech, Oak, and Maple mixed in, all skip planed to maximize their rugged patina and saw marks. On a floor this begs for heavy traffic, hiding even the heaviest wear in its mix of colors and textures. Ranging from deepest black-

brown to light tan, every plank speaks to the previous life of this mix of reclaimed woods—perfect



Pioneer Millworks Mixed Hardwoods—Settlers' Plank

CUT AND PASTE SPECIFICATION INTO APPROPRIATE CSI DIVISION

09 64 29—Wood Strip and Plank Flooring 06 42 00—Wood Paneling

MANUFACTURER

Pioneer Millworks 1180 Commercial Drive Farmington, NY 14425 Phone: 800-951-9663 Pioneer Millworks 2609 SE 6th Avenue Portland, OR 97202 Phone: 503-719-4800

MATERIALS

- 1. Product Name: Settlers' Plank Mixed Hardwoods
- 2. Species/Description: Domestic Hardwoods with original patina
- 3. Source: Agricultural/Industrial deconstruction
- Color: Tones may range from gold to brown to grey.
 Unlimited color variation is inherent to the product.
- 5. Grade: Settlers' Plank
- 6. Dimensions:

Solid TH—3/4"

WD—3" to 10" as specified

LG—18" to 144" random Engineered

TH—5/8"

WD—4" to 8" as specified

LG—12" to 96" random

- 7. Milling: Tongue and Groove Square Edge (TGSQE)
- 8. Finish: Unfinished unless specified otherwise
- 9. Hardness: 770-1450

(Janka Ball Test ASTM D1037-96A, Natural wood products have no minimum hardness since hardness is a characteristic of species and cannot be controlled)

10. FSC Claim: (SCS-COC-003998) Solid: Recycled 100% Engineered: FSC Mix 70%

ADDITIONAL INFORMATION

Heartwood: No restriction **Grain:** No restriction

Knots: No limitations on sound knots, surface defects from chipped

or open knots may be present.

Texture: This mixture shows a varied pattern of saw marks, wear patterns, colors and textures. Up to 30% of boards may be free of patina, with a mix of rough sawn and planed faces.

Overwood of up to 1/8" can be expected.

Voids: Nail, bolt and other mechanical holes can be present and occasionally reach 1" in diameter. Surface defects from insect marks, including pin holes may be present. Peg or bolt holes are

often left open in longer planks.

Discoloration: Ferrous staining from previous fasteners may be present.

Checks: Structural checks not affecting the integrity of the plank,
once installed, are allowed and more prevalent as the width of

the material increases.

Moisture Content: Kiln dried 6-9% prior to milling.

LEED INFORMATION

MRc3: Materials Reuse

(materials used for this credit cannot be applied to MRc4 or MRc5) MRc4: Recycled Content, 100% Post-Consumer Recycled Content (materials used for this credit cannot be applied to MRc3 or MRc7)

MRc5: Regional Materials (call for details)

MRc7: Solid Materials are FSC Recycled 100%; Engineered FSC Mix 70%

RECOMMENDED OVERAGE

Recommend 7–12% additional material for on-site grading, trimming and installation factors.



















Information is deemed reliable but subject to change. All photos for representation only. Additional information available at our website or call our wood design experts.