

Sports Collection—Bleacher Board

Pioneer millworks
RECLAIMED & SUSTAINABLE WOOD PRODUCTS



We salvage our Bleacher Board from athletic facilities all over the country and so you'll find a range of character and color—fir to pine. Solid widths and laminated strips, seat numbers and original graffiti all have a place in this fun mix.



Serving North America From Oregon and New York | (800) 951-9663 | pionermillworks.com

Pioneer Millworks Sports Collection—Bleacher Board

2/2018

CUT AND PASTE SPECIFICATION INTO APPROPRIATE CSI DIVISION

09 64 29—Wood strip and plank flooring

06 42 00—Wood Paneling

MANUFACTURER

Pioneer Millworks
1180 Commercial Drive
Farmington, NY 14425
Phone: 800-951-9663

Pioneer Millworks
2609 SE 6th Avenue
Portland, OR 97202
Phone: 503-719-4800

MATERIALS

1. **Product Name:** Bleacher Board
2. **Species/Description:** Domestic Douglas fir and/or Southern Yellow Pine, original patina.
3. **Source:** Bleachers reclaimed from athletic facilities.
4. **Color:** Tones may range from amber to brown.
Unlimited color variation is inherent to the product.
5. **Grade:** Original Gym Flooring
6. **Dimensions:**
Solid
TH—3/4" or 1" per batch (as-found), 3/4" (milled flooring)
WD—8" to 10" (as-found), 8 1/4" (milled flooring)
LG—24" to 144" random
Engineered
TH— N.A.
WD— N.A.
LG— N.A.
7. **Milling:** As-found or Tongue and Groove Square Edge (TGSQE)
8. **Finish:** Unfinished unless specified otherwise.
9. **Hardness:** 420–870
(Janka Ball Test ASTM D1037-96A, Natural wood products have no minimum hardness since hardness is a characteristic of species and cannot be controlled)
10. **FSC Claim:** (SCS-COC-003998)
Solid: Recycled 100%
Engineered: N.A.

ADDITIONAL INFORMATION

Heartwood: No restriction

Grain: Clear

Knots: Infrequent sound knots may be present.

Texture: Areas of peeling or flaking finish may be present.
Overwood should be expected after installation.

Voids: Boards will have repeating 1/4" carriage bolt holes.

Discoloration: Original finish and occasional paint marks will be intact.

Checks: No checking permitted.

Moisture Content: Kiln dried 6–9% prior to milling.

LEED INFORMATION

MRc3: Materials Reuse

(materials used for this credit cannot be applied to MRc4 or MRc5)

MRc4: Recycled Content, 100% Post-Consumer Recycled Content

(materials used for this credit cannot be applied to MRc3 or MRc7)

MRc5: Regional Materials (call for details)

MRc7: Solid Materials are FSC Recycled 100%

RECOMMENDED OVERAGE

Recommend 7–12% additional material for on-site grading, trimming and installation factors.



The mark of responsible forestry



Information is deemed reliable but subject to change. All photos for representation only. Additional information available at our website or call our wood design experts.