

# American Prairie—Corral Board



*Pioneer millworks*  
RECLAIMED & SUSTAINABLE WOOD PRODUCTS



Our American Prairie Corral Board is sourced from working cattle ranches across the Northern Great Plains. Long in length and naturally weathered grey, this material is ideal for siding applications.



# Pioneer Millworks American Prairie—Corral Board

1/1/2022

## CUT AND PASTE SPECIFICATION INTO APPROPRIATE CSI DIVISION

06 42 00—Wood Paneling  
07 46 23—Wood Siding

## MANUFACTURER

Pioneer Millworks East  
1180 Commercial Drive  
Farmington, NY 14425  
Phone: 800-951-9663

Pioneer Millworks West  
2655 NE Orchard Ave.  
McMinnville, OR 97128  
Phone: 503-437-9017

## MATERIALS

1. **Product Name:** American Prairie Corral Board
2. **Species/Description:** American Prairie Corral Board
3. **Source:** Agricultural deconstruction
4. **Color:** Tones may range from dark to silver grey. Unlimited color variation is inherent to the product.
5. **Grade:** Corral Board
6. **Dimensions:**
  - Solid**
    - TH— 5/8" to 1" variable
    - WD— 7" standard, widths up to 12" available upon request
    - LG— 24" to 16' random, called lengths available upon request
  - Engineered**
    - TH—N.A.
    - WD—N.A.
    - LG—N.A.
7. **Milling:** Ripped on two edges, sawn on one face (R2ER1S), shiplap and surfaced on 3 sides (S3S) available upon request
8. **Finish:** Unfinished unless specified otherwise
9. **Hardness:** 420–620  
(Janka Ball Test ASTM D1037-96A, Natural wood products have no minimum hardness since hardness is a characteristic of species and cannot be controlled)
10. **FSC Claim:** (SCS-COC-003998)
  - Solid:** FSC Recycled 100%
  - Engineered:** N.A.

## ADDITIONAL INFORMATION

**Heartwood:** No restriction.

**Grain:** No restriction.

**Knots:** No limitations on sound knots, surface defects from chipped or open knots may be present.

**Texture:** This mixture shows a varied pattern of saw marks, wear patterns, colors and textures. Overwood of up to 1/4" can be expected.

**Voids:** Fastener holes and open knots can be present and occasionally reach 2" in diameter. Surface defects from insect marks, including pin holes may be present.

**Discoloration:** Ferrous staining from previous fasteners may be present as well as occasional shadow marks where the surface wasn't exposed to weathering.

**Checks:** Structural checks not affecting the integrity of the plank, once installed, are allowed and more prevalent as the width of the material increases.

**Moisture Content:** Kiln dried 6–9% prior to milling.

## LEED INFORMATION

**MRc3:** Materials Reuse (materials used for this credit cannot be applied to MRc4 or MRc5)

**MRc4:** Recycled Content, 100% Post-Consumer Recycled Content (materials used for this credit cannot be applied to MRc3 or MRc7)

**MRc5:** Regional Materials (call for details)

**MRc7:** Solid Materials are FSC Recycled 100%

## RECOMMENDED OVERAGE

Recommend 7–12% additional material for on-site grading, trimming and installation factors.



The mark of responsible forestry



Information is deemed reliable but subject to change. All photos for representation only. Additional information available at our website or call our wood design experts.